

Primary # _____

HR # _____

Trinomial _____

NRHP Status Code 5D2

PRIMARY RECORD

Other Listings _____

Review Code _____

Reviewer _____

Date _____

Page 1 of 2

* Resource Name or #: 2411 30th Street, APN 539-031-03

P1. Other Identifier: _____

* P2. Location: ☐ Not for Publication ☒ Unrestricted

a. County San Diego

b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 2411 30th Street City San Diego Zip 92104

d. UTM: (Give more than one for large and/or linear feature) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, legal description, directions to resource, elevation, additional UTMs, etc. as app


Assessor's Parcel Number: 539-031-03; Legal Description: L3 BG TR1402/S 50 FT; Thomas Bros. Map
Reference: 60-F5

* P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
This house was built in 1924 in the Craftsman Bungalow style with neo-classical detailing. The house is one story with a Jerkinhead hipped gable roof and a gable end brick chimney. The exterior wall material is eight inch and three inch alternating horizontal wood siding. The portico roof is a Jerkin head hipped gable roof covered in composite shingles with a partial hexagon fascia. The portico is embellished with neo-classical dentils and pilasters that terminate into support brackets. The entry has a central glass door with sidelights flanked by Craftsman style wood framed with multi-lights and fixed panes. The house appears to have been recently painted with texture paint which is not consistent with the historical period, but could be restored in the future. The rear garage has original siding, however the garage door appears to have been added to with a living area. The house is located in the community of Burlingame. It is in good condition. The total usable floor area is 1,171 square feet. The house features 2 bedrooms and 1 bath. The total lot area is 5,800 square feet. Other improvements on the property include a detached garage.

* P3b. Resource Attributes: (List attributes and codes) HP2 Single family property

* P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)



P5b. Description of Photo: (View, date, etc.)

Photo Number: P0003020.JPG Est.

Date: 2001

* P6. Date Constructed/Age and Sources:

☐ Prehistoric ☒ Historic ☐ Both

1920'S Mid-City Survey Est.

1924 TRW Data Assessor

* P7. Owner and Address:

Brown Judy K

2411 30th St

San Diego CA 92104-5406

* P8. Recorded by: (Name, affiliation, address)

Ione Stiegler, IS Architecture

Updated 11/21/2001 by

City of San Diego Planning Staff

202 C Street, MS 4A San Diego CA 92101

* P9. Date Recorded: 07/15/1996

* P10. Survey Type: (Describe)

* P11. Report Citation: (Cite survey report/other sources or "none") _____

* Attachments: ☐ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record
☐ Photograph Record ☐ Other: (List) _____

BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 2

* NRHP Status Code 5D2

* Resource Name or #: 2411 30th Street, APN 539-031-03

B1. Historic Name:

B2. Common Name:

B3. Original Use: Residential SF

B4. Present Use: R--Residential (Single Family)

* B5. Architectural Style: Craftsman Bungalow

* B6. Construction History: (Construction date, alterations, and date of alterations.)

1920'S was the date of construction estimated from the field survey. Real estate data from TRW-Experian, based on Assessor's information, indicates that [19]24 was the date of construction.

* B7. Moved? ☐ No ☐ Yes ☒ Unknown Date _____ Original Location: _____

* B8. Related Features:

Related features on the property include a detached garage. The building is within the Burlingame Historic District.

B9a. Architect: Unknown

b. Builder: Unknown

* B10. Significance: Theme Architecture

Area San Diego

Period of Significance 1912-1952

Property Type Residential SF

Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The Burlingame Historical District consists of some forty acres of land, originally developed in 1912, extending along San Marcos Street to the north, Kalmia Street to the south, 32nd Street to the east, and 30th Street to the west. The tract's architectural significance is expressed in its curvilinear street plan, which follows the area's natural contours. The original planners, Joseph McFadden and George Buxton, demarcated it with rose-colored sidewalks, the only such area in the City of San Diego to do so. Limited access to the tract at the time of its incorporation has left it with a quality of an integrated and separate development distinct from the surrounding community. The tract is a major example of an early twentieth century local experimental approach to real estate development utilizing a "team of specialists" to develop, market and deal exclusive real estate property. Its developers were extremely active in local real estate development during this time. Architectural control was maintained through the use of consulting architect, William H. Wheeler, and restrictive building covenants. Later on, these controls would be enforced through the watchdog efforts of Burlingame Women's Club, allegedly the earliest and oldest neighborhood organization in San Diego. Located within the tract is an eclectic mix of over two hundred unique and interesting houses, each a representation of pre-World War One suburban residential architecture; including Craftsman, Mission, Spanish Colonial and Pueblo Revivals, as well as Prairie School, Art Deco, Ranch, Colonial Revival and many other individual hybrid combinations of several styles.

B11. Additional Resource Attributes: (List attributes and codes):

* B12. References:

San Diego Co. Assessor Map Book 539, Page 03, 1995-96 and TRW-Experian 1997.

McAlester & McAlester. "A Field Guide to American Houses". 1984.

Woodbridge, Sally B. "California Architecture", 1988.

B13. Remarks:

Zoning: R1-5; County land use code: 111

* B14. Evaluator: Ione Stiegler, IS Arch / City

Date of Evaluation: 07/15/1996

Updated 11/21/2001

(This space reserved for official comments.)



Primary #

HR #

Trinomial

NRHP Status Code 5D2

PRIMARY RECORD

Other Listings

Review Code

Reviewer

Date

Page 1 of 2

* Resource Name or #: 2425 30th Street, APN 539-031-02

P1. Other Identifier:

* P2. Location: ☐ Not for Publication ☒ Unrestricted

a. County San Diego

b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M.

c. Address 2425 30th Street City San Diego Zip 92104

d. UTM: (Give more than one for large and/or linear feature) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, legal description, directions to resource, elevation, additional UTM's, etc. as app

Assessor's Parcel Number: 539-031-02; Legal Description: L2 BG TR1402/EXC N 20 FT/ /EXC S 50 FT/*; Thomas Bros. Map Reference: 60-F5


* P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

This house was built in 1922 in the Craftsman Bungalow style. The house is one story with a Jerkinhead hipped gable roof. A brick chimney is located on the gable end. The exterior wall material is wood clapboard siding. A small, centered, Jerkinhead hipped gable roof porch projects over the main entry and is supported by tapered columns. All window glazing appears to be original throughout the house and are currently covered by security bars. A newly constructed balustrade encloses the porch. The house is located in the community of Burlingame. It is in good condition. The total usable floor area is 788 square feet. The house features 2 bedrooms and 1 bath. The total lot area is 5,700 square feet. Other improvements on the property include a detached garage.

* P3b. Resource Attributes: (List attributes and codes) HP2 Single family property

* P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)



P5b. Description of Photo: (View, date, etc.)

Photo Number: P0003019.JPG Est. Date: 2001

* P6. Date Constructed/Age and Sources:

☐ Prehistoric ☒ Historic ☐ Both

1920'S Mid-City Survey Est.

1922 TRW Data Assessor

* P7. Owner and Address:

O'braskv Kathryn

2425 30th St

San Diego CA 92104-5406

* P8. Recorded by: (Name, affiliation, address)

Ione Stiegler, IS Architecture

Updated 11/21/2001 by

City of San Diego Planning Staff

202 C Street, MS 4A San Diego CA 92101

* P9. Date Recorded: 07/15/1996

* P10. Survey Type: (Describe)

* P11. Report Citation: (Cite survey report/other sources or "none")

* Attachments: ☐ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record
☐ Photograph Record ☐ Other: (List) _____

BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 2

* NRHP Status Code 5D2

* Resource Name or #: 2425 30th Street, APN 539-031-02

B1. Historic Name:

B2. Common Name:

B3. Original Use: Residential SF

B4. Present Use: R--Residential (Single Family)

* B5. Architectural Style: Craftsman Bungalow

* B6. Construction History: (Construction date, alterations, and date of alterations.)

1920'S was the date of construction estimated from the field survey. Real estate data from TRW-Experian, based on Assessor's information, indicates that [19]22 was the date of construction, with effective improvements dating from [19]30.

* B7. Moved? ☐ No ☐ Yes ☒ Unknown Date _____ Original Location: _____

* B8. Related Features:

Related features on the property include a detached garage. The building is within the Burlingame Historic District.

B9a. Architect: Unknown

b. Builder: Unknown

* B10. Significance: Theme Architecture

Area San Diego

Period of Significance 1912-1952

Property Type Residential SF

Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The Burlingame Historical District consists of some forty acres of land, originally developed in 1912, extending along San Marcos Street to the north, Kalmia Street to the south, 32nd Street to the east, and 30th Street to the west. The tract's architectural significance is expressed in its curvilinear street plan, which follows the area's natural contours. The original planners, Joseph McFadden and George Buxton, demarcated it with rose-colored sidewalks, the only such area in the City of San Diego to do so. Limited access to the tract at the time of its incorporation has left it with a quality of an integrated and separate development distinct from the surrounding community. The tract is a major example of an early twentieth century local experimental approach to real estate development utilizing a "team of specialists" to develop, market and deal exclusive real estate property. Its developers were extremely active in local real estate development during this time. Architectural control was maintained through the use of consulting architect, William H. Wheeler, and restrictive building covenants. Later on, these controls would be enforced through the watchdog efforts of Burlingame Women's Club, allegedly the earliest and oldest neighborhood organization in San Diego. Located within the tract is an eclectic mix of over two hundred unique and interesting houses, each a representation of pre-World War One suburban residential architecture; including Craftsman, Mission, Spanish Colonial and Pueblo Revivals, as well as Prairie School, Art Deco, Ranch, Colonial Revival and many other individual hybrid combinations of several styles.

B11. Additional Resource Attributes: (List attributes and codes):

* B12. References:

San Diego Co. Assessor Map Book 539, Page 03, 1995-96 and TRW-Experian 1997.

McAlester & McAlester. "A Field Guide to American Houses". 1984.

Woodbridge, Sally B. "California Architecture", 1988.


B13. Remarks:

Zoning: R1-5; County land use code: 111

* B14. Evaluator: Ione Stiegler, IS Arch / City

Date of Evaluation: 07/15/1996 Updated 11/21/2001

(This space reserved for official comments.)



Primary # _____

HR # _____

Trinomial _____

NRHP Status Code 5D2

PRIMARY RECORD

Other Listings _____

Review Code _____ Reviewer _____

Date _____

Page 1 of 2

* Resource Name or #: 2511 30th Street, APN 543-711-04

P1. Other Identifier: _____

* P2. Location: ☐ Not for Publication ☒ Unrestricted

a. County San Diego

b. USGS 7.5' Quad _____ Date _____ T. _____; R. _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 2511 30th Street City San Diego Zip 92104

d. UTM: (Give more than one for large and/or linear feature) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, legal description, directions to resource, elevation, additional UTM's, etc. as app


Assessor's Parcel Number: 543-711-04

* P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
This house was built in the 1920's in the Mission Revival style. The house is one story with a flat roof, parapet walls, cantilevered roofs, and terra cotta drains. The porch has a projecting bay with a low-point arch entryway and recessed porch. The porch is connected to a rectangular walled patio. A tapered chimney is located on the north side of the house. All windows are wood-framed, double-hung with upper multi-lights that appear to be original. The house is setback and slopes upward approximately eight feet above the sidewalk and is accessed by concrete steps and wrought iron railing. The property features mature landscaping with complimentary plants. The garage structure is original and has single car garage barn-type portals. The house is located in the community of Burlingame. It is in excellent condition.

* P3b. Resource Attributes: (List attributes and codes) HP2 Single family property

* P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)



P5b. Description of Photo: (View, date, etc.)

Photo Number: P0003018.JPG Est. Date: 2001

* P6. Date Constructed/Age and Sources:

☐ Prehistoric ☒ Historic ☐ Both

1920'S Mid-City Survey Est.

* P7. Owner and Address:

Koch, Jeffrey G And Nalini P

2511 30th St

San Diego CA 92104-5406

* P8. Recorded by: (Name, affiliation, address)

Ione Stiegler, IS Architecture

Updated 11/21/2001 by

City of San Diego Planning Staff

202 C Street, MS 4A San Diego CA 92101

* P9. Date Recorded: 07/15/1996

* P10. Survey Type: (Describe)

* P11. Report Citation: (Cite survey report/other sources or "none") _____

* Attachments: ☐ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record
☐ Photograph Record ☐ Other: (List) _____

BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 2

* NRHP Status Code 5D2

* Resource Name or #: 2511 30th Street, APN 543-711-04

B1. Historic Name:

B2. Common Name:

B3. Original Use: Residential SF

B4. Present Use: R--Residential (Single Family)

* B5. Architectural Style: Mission Revival

* B6. Construction History: (Construction date, alterations, and date of alterations.)

1920'S was the date of construction estimated from the field survey.

* B7. Moved? ☐ No ☐ Yes ☒ Unknown Date _____ Original Location: _____

* B8. Related Features:

The building is within the Burlingame Historic District.

B9a. Architect: Unknown

b. Builder: Unknown

* B10. Significance: Theme Architecture

Area San Diego

Period of Significance 1912-1952

Property Type Residential SF

Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The Burlingame Historical District consists of some forty acres of land, originally developed in 1912, extending along San Marcos Street to the north, Kalmia Street to the south, 32nd Street to the east, and 30th Street to the west. The tract's architectural significance is expressed in its curvilinear street plan, which follows the area's natural contours. The original planners, Joseph McFadden and George Buxton, demarcated it with rose-colored sidewalks, the only such area in the City of San Diego to do so. Limited access to the tract at the time of its incorporation has left it with a quality of an integrated and separate development distinct from the surrounding community. The tract is a major example of an early twentieth century local experimental approach to real estate development utilizing a "team of specialists" to develop, market and deal exclusive real estate property. Its developers were extremely active in local real estate development during this time. Architectural control was maintained through the use of consulting architect, William H. Wheeler, and restrictive building covenants. Later on, these controls would be enforced through the watchdog efforts of Burlingame Women's Club, allegedly the earliest and oldest neighborhood organization in San Diego. Located within the tract is an eclectic mix of over two hundred unique and interesting houses, each a representation of pre-World War One suburban residential architecture; including Craftsman, Mission, Spanish Colonial and Pueblo Revivals, as well as Prairie School, Art Deco, Ranch, Colonial Revival and many other individual hybrid combinations of several styles.

B11. Additional Resource Attributes: (List attributes and codes):

* B12. References:

San Diego Co. Assessor Map Book 543, Page 71, 1995-96 and TRW-Experian 1997.

McAlester & McAlester. "A Field Guide to American Houses", 1984.


Woodbridge, Sally B. "California Architecture", 1988.

B13. Remarks:

* B14. Evaluator: Ione Stiegler, IS Arch / City

Date of Evaluation: 07/15/1996 Updated 11/21/2001

(This space reserved for official comments.)



PRIMARY RECORD

Other Listings

Review Code

Reviewer

Date

Page 1 of 2

* Resource Name or #: 2513 30th Street, APN 543-711-03

P1. Other Identifier:

* P2. Location: ☐ Not for Publication ☒ Unrestricted

a. County San Diego

b. USGS 7.5' Quad Date T ; R ; 1/4 of 1/4 of Sec ; B.M.

c. Address 2513 30th Street City San Diego Zip 92104

d. UTM: (Give more than one for large and/or linear feature) Zone mE/ mN

e. Other Locational Data: (e.g. parcel #, legal description, directions to resource, elevation, additional UTM's, etc. as app


Assessor's Parcel Number: 543-711-03

* P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
This house was built in 1932 in the Spanish Colonial Revival style. The house is one story with low-pitch, barrel clay tile roof, double projection round vents and an abutting chimney. The exterior wall material is stucco. The entry has a wide, low-point arch. All windows are double-hung and appear to be original. The side of the house has diagonally-cut rectangular brackets supporting drains. The rear of the house may be an early addition. The house is raised approximately four feet from the sidewalk and the garage is flush with the house. The house is located in the community of Burlingame. It is in good condition. The total usable floor area is 990 square feet. The total lot area is 3,600 square feet.

* P3b. Resource Attributes: (List attributes and codes) HP2 Single family property

* P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)



P5b. Description of Photo: (View, date, etc.)

Photo Number: P0003017.JPG Est. Date: 2001

* P6. Date Constructed/Age and Sources:

☐ Prehistoric ☒ Historic ☐ Both

1932'S Mid-City Survey Est.

1932 TRW Data Assessor

* P7. Owner and Address:

Byrne, Dennis

2513 30th St

San Diego CA 92104-5406

* P8. Recorded by: (Name, affiliation, address)

Jone Stiegler, IS Architecture

Updated 11/21/2001 by

City of San Diego Planning Staff

202 C Street, MS 4A San Diego CA 92101

* P9. Date Recorded: 07/15/1996

* P10. Survey Type: (Describe)

* P11. Report Citation: (Cite survey report/other sources or "none")

* Attachments: ☐ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record
☐ Photograph Record ☐ Other: (List)

BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 2

* NRHP Status Code 5D2

* Resource Name or #: 2513 30th Street, APN 543-711-03

B1. Historic Name:

B2. Common Name

B3. Original Use: Residential SF

B4. Present Use: R--Residential (Single Family)

* B5. Architectural Style: Spanish Colonial Revival

* B6. Construction History: (Construction date, alterations, and date of alterations.)

1920'S was the date of construction estimated from the field survey.

* B7. Moved? ☐ No ☐ Yes ☒ Unknown Date _____ Original Location: _____

* B8. Related Features:

The building is within the Burlingame Historic District.

B9a. Architect: Unknown

b. Builder: Unknown

* B10. Significance: Them Architecture

Area San Diego

Period of Significance 1912-1952

Property Type Residential SF

Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The Burlingame Historical District consists of some forty acres of land, originally developed in 1912, extending along San Marcos Street to the north, Kalmia Street to the south, 32nd Street to the east, and 30th Street to the west. The tract's architectural significance is expressed in its curvilinear street plan, which follows the area's natural contours. The original planners, Joseph McFadden and George Buxton, demarcated it with rose-colored sidewalks, the only such area in the City of San Diego to do so. Limited access to the tract at the time of its incorporation has left it with a quality of an integrated and separate development distinct from the surrounding community. The tract is a major example of an early twentieth century local experimental approach to real estate development utilizing a "team of specialists" to develop, market and deal exclusive real estate property. Its developers were extremely active in local real estate development during this time. Architectural control was maintained through the use of consulting architect, William H. Wheeler, and restrictive building covenants. Later on, these controls would be enforced through the watchdog efforts of Burlingame Women's Club, allegedly the earliest and oldest neighborhood organization in San Diego. Located within the tract is an eclectic mix of over two hundred unique and interesting houses, each a representation of pre-World War One suburban residential architecture; including Craftsman, Mission, Spanish Colonial and Pueblo Revivals, as well as Prairie School, Art Deco, Ranch, Colonial Revival and many other individual hybrid combinations of several styles.

B11. Additional Resource Attributes: (List attributes and codes):

* B12. References:

San Diego Co. Assessor Map Book 543, Page 71, 1995-96 and TRW-Experian 1997.

McAlester & McAlester. "A Field Guide to American Houses". 1984.

Woodbridge, Sally B. "California Architecture", 1988.

B13. Remarks:

* B14. Evaluator: Jone Stiegler, IS Arch / City

Date of Evaluation: 07/15/1996 Updated 11/21/2001

(This space reserved for official comments.)



Primary # _____
HR # _____
Trinomial _____
NRHP Status Code SS3

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

* Resource Name or #: 2515 30th Street, APN 453-711-02

P1. Other Identifier: _____


* P2. Location: ☐ Not for Publication ☒ Unrestricted
a. County San Diego
b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 2515 30th Street City San Diego Zip 92104
d. UTM: (Give more than one for large and/or linear feature) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g. parcel #, legal description, directions to resource, elevation, additional UTMs, etc. as app
Assessor's Parcel Number: 453-711-02; Legal Description: L2 BH TR1402/N 51 FT; Thomas Bros. Map
Reference: 60-F5

* P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
This house was built in 1936 in the Spanish Colonial Revival style. The house is one story with a flat roof, parapet walls, a central tapered chimney, and single round vents. The exterior wall material is stucco. The side entry has a tower element with a tile roof and a balconet. The entrance has an original solid wood door with four lights in the upper portion. All windows have been changed to vinyl, sliding, or double-hung. The house is raised five feet from the sidewalk and is accessed by scored concrete steps. The house is located in the community of Burlingame. It is in fair condition. The total usable floor area is 711 square feet. The total lot area is 4,400 square feet.

* P3b. Resource Attributes: (List attributes and codes) HP2 Single family property

* P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)



P5b. Description of Photo: (View, date, etc.)

Photo Number: P0003015.JPG Est. Date: 2001

* P6. Date Constructed/Age and Sources:
☐ Prehistoric ☒ Historic ☐ Both

1936 TRW Data Assessor

* P7. Owner and Address:

Grass Urban J & Rathe Paul M
2515 30th St
San Diego Ca 92104-4947

* P8. Recorded by: (Name, affiliation, address)

Ione Stiegler, IS Architecture
Updated 11/21/2001 by
City of San Diego Planning Staff
202 C Street, MS 4A San Diego CA 92101

* P9. Date Recorded: 07/15/1996

* P10. Survey Type: (Describe)

* P11. Report Citation: (Cite survey report/other sources or "none") _____

* Attachments: ☐ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record
☐ Photograph Record ☐ Other: (List) _____

BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 2

* NRHP Status Code 5S3

* Resource Name or #: 2515 30th Street, APN 453-711-02

B1. Historic Name: _____

B2. Common Name: _____

B3. Original Use: Residential S

B4. Present Use: (Sfr)

* B5. Architectural Style: Spanish Colonial Revival

* B6. Construction History: (Construction date, alterations, and date of alterations.)

was the date of construction estimated from the field survey. Real estate data from TRW-Experian, based on Assessor's information, indicates that [19]1936 was the date of construction.

* B7. Moved? ☐ No ☐ Yes ☒ Unknown Date _____ Original Location: _____

* B8. Related Features:

The building is within the Burlingame Historic District.

B9a. Architect: Unknown

b. Builder: Unknown

* B10. Significance: Them Architecture

Area San Diego

Period of Significance 1912-1952

Property Type _____

Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The Burlingame Historical District consists of some forty acres of land, originally developed in 1912, extending along San Marcos Street to the north, Kalmia Street to the south, 32nd Street to the east, and 30th Street to the west. The tract's architectural significance is expressed in its curvilinear street plan, which follows the area's natural contours. The original planners, Joseph McFadden and George Buxton, demarcated it with rose-colored sidewalks, the only such area in the City of San Diego to do so. Limited access to the tract at the time of its incorporation has left it with a quality of an integrated and separate development distinct from the surrounding community. The tract is a major example of an early twentieth century local experimental approach to real estate development utilizing a "team of specialists" to develop, market and deal exclusive real estate property. Its developers were extremely active in local real estate development during this time. Architectural control was maintained through the use of consulting architect, William H. Wheeler, and restrictive building covenants. Later on, these controls would be enforced through the watchdog efforts of Burlingame Women's Club, allegedly the earliest and oldest neighborhood organization in San Diego. Located within the tract is an eclectic mix of over two hundred unique and interesting houses, each a representation of pre-World War One suburban residential architecture; including Craftsman, Mission, Spanish Colonial and Pueblo Revivals, as well as Prairie School, Art Deco, Ranch, Colonial Revival and many other individual hybrid combinations of several styles.

B11. Additional Resource Attributes: (List attributes and codes): _____

* B12. References:

San Diego Co. Assessor Map Book 453, Page 71, 1995-96 and TRW-Experian 1997.

McAlester & McAlester. "A Field Guide to American Houses". 1984.

Woodbridge, Sally B. "California Architecture", 1988.

B13. Remarks:

Zoning: R1-5; County land use code: 111

* B14. Evaluator: Ione Stiegler, IS Arch / City

Date of Evaluation: 07/15/1996 Updated 11/21/2001

(This space reserved for official comments.)

